



SafeBuy's Pre-Purchase Comprehensive Vehicle Inspection Report

10 Nov 2025 / Inspector 3 / SBCDKD472 / Comprehensive Inspection

Complete

Flagged items	2
Booking code	SBCDKD472
Conducted on	10.11.2025 13:30 AEDT
Prepared by	Inspector 3
Service type	Comprehensive Inspection
Location	62 Bank St, South Melbourne VIC 3205, Australia (-37.832084099999996, 144.9673334)
Buyer's name	Michael Nguyen
Email	mn008@outlook.com
Buyer's contact	0413008090
Seller's name	Blake Ritchie
Seller's contact	0407119261

Flagged items

2 flagged

Exhaust, Suspension, Brakes and Steering

LHF tyre

Need Attention

Air pressure low



Photo 52



Photo 53



Photo 54

Interior

Front and rear seats heater & operation / seats condition

Need Attention

Cup holder lid stuck

Scratch on passenger seat



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127

Vehicle Details	
Car make	BMW
Car model and Badge	I40M50
Registration no.	DKD472
State	VIC
Compliance	01/2025
Colour	Grey
Odometer reading	3800
  Photo 1 Photo 2	
Engine number	R933B440
VIN	WBY32AW020FS46032
  Photo 3 Photo 4	
No. of doors	4
Number of cylinders	6
Transmission type	Automatic
Engine Type	Petrol
Notes	

Engine & ECU Scan

Battery test and battery terminals and bracket

Good



Photo 5

Alternator operation

Good



Photo 6

Radiator pressure test

Not Applicable

Radiator, Radiator fan and Hoses

Good



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11

Thermostate housing and water pump

Good



Photo 12



Photo 13



Photo 14

Coolant condition

Good



Photo 15



Photo 16

Heater hoses & heater core

Good



Photo 17



Photo 18

A/C condenser, compressor & lines

Good



Photo 19



Photo 20

Drive belt and tensioner

Not Applicable

Power steering pump and hoses

Not Applicable

Electronic power steering

Good

Fuel pump / fuel line / fuel injectors

Not Applicable

Welsh plugs

Not Applicable

Starter motor

Not Applicable

Intake manifold

Good

Engine fuse box

Good

Washer bottle

Good

Oil cap deposit and oil condition

Not Applicable

Engine oil leak

Not Applicable

Engine mounts

Good



Photo 21



Photo 22



Photo 23

Turbo charger

Not Applicable

Super charger

Not Applicable

LPG system

Good

Misfire in engine / pressure test

Not Applicable




Cold / hot engine runs and engine health

Not Applicable

Head gasket leakage

Not Applicable

ECU Scan	Good
Hybrid battery condition	Good
Hybrid invertor	Good
Notes	

Drive Line	
Gear Box / transmission mounts	Not Applicable
Transmission oil condition	Not Applicable
Clutch / Clutch pedal and slave cylinder	Not Applicable
Driveshaft and boots condition	Good
      Photo 24 Photo 25 Photo 26 Photo 27 Photo 28 Photo 29     Photo 30 Photo 31 Photo 32 Photo 33	
Transfer case / Front differential /Centre differential	Not Applicable
Rear differential & Tail shaft	Good
Leaf / coil springs	Not Applicable
Drive line images	
      Photo 34 Photo 35 Photo 36 Photo 37 Photo 38 Photo 39    Photo 40 Photo 41 Photo 42	
Note	

Exhaust, Suspension, Brakes and Steering		1 flagged
Exhaust manifold / mufflers and catalytic convertor		Not Applicable
Exhaust smoke		Not Applicable
Brake master		Good
RHF tyre		Good
   Photo 43 Photo 44 Photo 45		
RHR tyre		Good
   Photo 46 Photo 47 Photo 48		
LHR tyre		Good
   Photo 49 Photo 50 Photo 51		
LHF tyre		Need Attention
Air pressure low    Photo 52 Photo 53 Photo 54		
Front brake discs		Good
 Photo 55		
Front brake pads		Good
 Photo 56		
Rear brake discs		Good




Photo 57

Rear disc / drum brakes

Good



Photo 58

Brake caliper, cylinders and hoses

Good



Photo 59



Photo 60

Sway bar links and torsion bar

Good



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65

Steering knuckle / Steering arms / tie rod ends

Good




Photo 66



Photo 67




Photo 68



Photo 69



Photo 70

Ball joints

Good



Photo 71



Photo 72



Photo 73

Shock absorber / struts

Good



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80

Suspension bushes / Control Arm bushes

Good



Photo 81



Photo 82



Photo 83



Photo 84

Hub assembly / wheel bearings

Good

Notes

Please note that some workshops will suggest to replace the brake pads as early as 40% - 50% remaining.

Body, Panels and Lights

Windscreen, bonnet and bonnet struts

Good



Photo 85



Photo 86

Park / low & high beam / reverse / brake/ repeater / fog lenses / globes

Good



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91

Side mirrors

Good

Door lock and keys

Good

Glass / trim / weather seals / rubber / mould strips

Good

Doors / Door seals

Good



Photo 92



Photo 93



Photo 94




Photo 95



Photo 96



Photo 97

Fuel cap

Good



Photo 98

Rear bumper / Boot & tailgate struts

Good



Photo 99



Photo 100

Notes

Interior				1 flagged
Carpet condition / floor mats / rubber pedals / dashboard				Good
				
Photo 101	Photo 102	Photo 103	Photo 104	
Glove box / air vents				Good
				
Photo 105	Photo 106	Photo 107		
Centre consol / lids				Good
				
Photo 108	Photo 109	Photo 110	Photo 111	Photo 112
Roof lining / Sun roof				Good
				
Photo 113	Photo 114	Photo 115	Photo 116	Photo 117
Sun visors / interior light/ Rear view Mirror				Good
				
Photo 118				
Comb. switch / hazard light switch				Good
Windows operation				Good
Front and rear wiper inserts / Washers				Good
Fan speed control / air blower				Good
Heater operation				Good
Air condition operation				Good
Head unit / CD Player / Radio / Navigation				Good

Steering wheel grip / horn

Good



Photo 119

Park brake operation

Good

Seat belts

Good

Front and rear seats heater & operation / seats condition

Need Attention

Cup holder lid stuck
Scratch on passenger seat



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127

Fuel guages / temp gauges

Good



Photo 128



Photo 129



Photo 130

Warning lights

Good

Notes

Road Test Report	
Clutch / auto trans operation	Good
Trans flare / differential whine	Good
Brake (ABS) operation & brake shudder	Good
Road noise and handling / Wheel Alignment	Good
Driveshafts vibration / Steering vibration	Good
Gear Box Synchronesh 4x4 High and Low	Not Applicable
Speedo / odometer	Good
Trip meter / Cruise control / blind spot sensor / Lane Assistance	Good
Turbo charger / super charger	Not Applicable
Engine performance / engine smoke	Good
Hybrid / electric battery operation	Good
	
Photo 131	
Road speed limit when tested	60kmh
Vehicle general drivability	Good
Notes	

Vehicle Condition Report

Condition Report



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139



Photo 140

Cosmetic Panel / paint, Scratches / Dents, Damage and Rust will be marked in a color different than vehicle's paint. Also find description in a note.

Please Note:

This inspection will not make comment on the alignment of any parts or body panels and will not be able to detect if any part of the vehicle is bent or out of its original shape. If you have any possible concerns with these items, please arrange an inspection by a registered smash repairer. SafeBuy will note larger type damage and previous accident repairs to all vehicles when conducting a premium inspection.

However, smaller shopping size dents, scratches or hail damage will not be noted or guaranteed due to our mobile service encountering dirty, unwashed and wet vehicles and lighting conditions on site. It is the purchaser's responsibly to re - check the inspected vehicle personally, before settlement.

Notes

Lhr wheel edges scraped.
Stope chip on bumper
Stone chip on rhr wheel arch
Minor scratch on rh side skirt.



Photo 141



Photo 142



Photo 143



Photo 144



Photo 145

Inspection Report Summary

Body/Exterior Rating	90%
----------------------	-----

Interior rating	90%
-----------------	-----

Mechanical rating	95%
-------------------	-----

Summary of above rating

Exterior: wheel edge, stone chips and Minor scratch. Interior: cup holder lid and a scratch on passenger seat. Mechanical: service due in jan

Recommendation from Inspector

This inspection indicates the general vehicle condition is

Good

Sign by the inspector



10.11.2025 16:01 AEDT

Note:

This is Dealer's inspection report. this report consist of brief interior, exterior and mechanical inspection. this report also included ECU Scan. Incase of any faults mentioned in report please enquire with dealer. For any other enquiry contact: customercare@safebuy.com.au

Inspection rating system is explained below:

From 90-95% above is good.
80%-90% is Fair.
70%-80% below average and
Below 70% is poor condition.

Over all rating:

good + good + fair = good
good + fair + fair = fair
good + below average + fair = fair
fair+fair+below average = below average
below average+below average+fair=poor

This vehicle has been assessed taking into consideration the kms displayed, the vehicle age and the condition of the vehicle.

Buyer Responsibilities:

All vehicles are inspected as presented. In many cases vehicles are dirty / unwashed etc. Please ensure to read this report in full including any added notes which may point out any repairs, servicing, faults and problem. Further explanation of the report is made by speaking directly with your Dealer.

This inspection report is a condition report which identify issues in a vehicle presented at time of inspection. For diagnosis, part and labour required to fix issues please contact your local mechanic or dealer.

BEWARE: Always check for a clear title before purchasing a vehicle especially on private sales.

Our report is not a roadworthy or safety certificate of any kind, which may be needed in some states for vehicle registration purposes.

The vehicle's authenticity / verification is solely the responsibility of the buyer.

Engine number will only be recorded from the engine if its clearly visible, otherwise copied from registration records.

Items on any report only be tested if applicable to vehicle.

Inspector follows a report checklist, further check/diagnoses is recommended for any concern found.

Buyers to check with the relevant authorities of Australia wide for any type of write-off SafeBuy gives no guarantees on previous repair history nor is the vehicle's Body structure damage or components.

A final visual inspection of a vehicle at the time of sale transaction is the responsibility of the buyer.

SafeBuy will not be liable for any dents/ damage or condition change after the inspection report. Please have a report handy to telly condition. Otherwise contact SafeBuy for assistance.

Please refer to manufacturer's specifications for replacement of Timing belts, and filters in service records.

We do not inspect the engine internals, which include fuel injectors, EGR valves nor how much sludge or carbon build up. Which normally found in diesel engines, especially in the high kilometer's vehicles.

We do not check or decode tyres fitted, age, load rating and the manufacturer's specified oils, fluids and coolants and recalls from manufacturer. Inspection and assessment by only visual and noise detection no adjustment has been made, nor components dismantled to confirm diagnosis. Whilst every care is taken SafeBuy will not be responsible for any intermittent problem which does not appear during the inspection.

This report is not a warranty or guarantee, it is only intended for the person mentioned in the report and it is not to be relied upon by any other person(s) or purpose.

SafeBuy inspection report is a condition report which help customer to make their decision in order to buy or sell a vehicle. The decision to purchase a vehicle is customer own decision in regards to their own investigations and enquiries.

Media summary




Photo 1




Photo 2



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19




Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31




Photo 32



Photo 33




Photo 34



Photo 35




Photo 36



Photo 37



Photo 38



Photo 39



Photo 40




Photo 41



Photo 42



Photo 43




Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52




Photo 53



Photo 54



Photo 55



Photo 56




Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63




Photo 64



Photo 65




Photo 66



Photo 67




Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74




Photo 75



Photo 76



Photo 77




Photo 78




Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86




Photo 87



Photo 88




Photo 89




Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127



Photo 128



Photo 129




Photo 130




Photo 131




Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143



Photo 144



Photo 145