

# Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

## Repair Shop

Shop Name:SafeBuy  
 Address:CBD Melbourne Victoria  
 Zip Code:3000  
 Telephone:0386767692  
 Email:admin@safe-buy.com.au  
 SN:985596001700  
 Test Time:2021-01-12 10:45:04  
 Technician Name:SafeBuy Tech1



## Vehicle Information

Year:2009  
 Make:Toyota  
 Model:PRIUS  
 VIN:JF1...  
 Engine Size:2...  
 Odometer:174184.00  
 Vehicle Software Version:V49.80  
 Diagnostic Application Version:V5.00.003  
 Diagnostic path:16PIN DLC(Europe and Other) > Prius > ZVW3# > Others > -2010.11 > Others



## Inspection Result

Hybrid Control 2 problems exist

- |                                |         |
|--------------------------------|---------|
| 1.P3000 Battery Control System | Current |
| 2.P3000 Battery Control System | History |

ABS/VSC/TRC 1 problems exist

- |  |         |
|--|---------|
| 1.C1241 Low or High Power Supply Voltage | Current |
|--|---------|

The following systems are OK:

- 1.Engine and ECT
- 2.Cruise Control
- 3.Transmission Control
- 4.EMPS
- 5.SRS Airbag
- 6.Air Conditioner
- 7.Combination Meter
- 8.Main Body
- 9.HL AutoLeveling
- 10.D-Door Motor
- 11.P-Door Motor

- 12.RL-Door Motor
- 13.RR-Door Motor
- 14.Sliding Roof
- 15.Navigation System
- 16.PM1 Gateway
- 17.PM2 Gateway
- 18.Master Switch
- 19.Entry&Start
- 20.Power Source Control
- 21.IPA/Parking Assist Monitor