



Report No.:D0095679295

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: WBY32AW020F*****

Vehicle manufacturer/model: BMW_EV/i4 M50

Year of manufacture: 2023.12

Odometer: 3794

Vehicle Software Version: V51.66

Repair State: 1

Inspection Organization

Name: SafeBuy

Address: 582 Little Collins Street, Melbourne, Vic 3000

Contact Number: [0386767692](tel:0386767692)

SN: 979510001239

Time and date of inspection: 2025-11-10 15:16:18



Inspection Result

Inspections are normal for Vehicle body system

- 1.FAS (Seat Module, Driver)
- 2.A/C (Air Conditioning - IHKA)
- 3.EME2 (Electrical Machine Electronics 2)
- 4.ACC (Active Cruise Control)
- 5.ZBE/CON (Controller)
- 6.HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- 7.I HMI (LED Main Light Module Left)



Professional Report

FAS (Seat Module, Driver) Normal ▾

A/C (Air Conditioning - IHKA) Normal ▾

EME2 (Electrical Machine Electronics 2) Normal ▾

ACC (Active Cruise Control) Normal ▾

ZBE/CON (Controller) Normal ▾

HKFM/HKL (Automatic Luggage Compartment Lid Actuation) Normal ▾

LHML (LED Main Light Module, Left) Normal ▾

SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM) Normal ▾

FZD (Function Center, Roof) Normal ▾

ZGM (Central Gateway Module) Normal ▾

AMP (Amplifier) Normal ▾

LIM (Charging Interface Module) Normal ▾

ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System) Normal ▾



VDC/VDM (Vertical Dynamics Management)	Normal ▾
TRSVc (All Round View Camera)	Normal ▾
ABS (Anti-Lock Braking System - DSC)	Normal ▾
TEE2 (Electrical Machine Electronics 2)	Normal ▾
PMA (Parking Assistant)	Normal ▾
RDC (Tyre Pressure Control)/SRR_VR (Side Radar Sensor Near Range Front Right)	Normal ▾
CIC (Car Information Computer)	Normal ▾
SRR_VL (Side Radar Sensor Near Range Front Left)	Normal ▾
LHMR (LED Main Light Module, Right)	Normal ▾
IC (Instrument Cluster - INSTR)	Normal ▾
ECALL (Emergency Call)	Normal ▾
KAFAS (Camera Based Driver Assist Systems)	Normal ▾
SME (Battery Management Electronics)	Normal ▾
EPS (Electronic Power Steering)	Normal ▾



LHMR (LED Main Light Module, Right)	Normal ▾
IC (Instrument Cluster - INSTR)	Normal ▾
ECALL (Emergency Call)	Normal ▾
KAFAS (Camera Based Driver Assist Systems)	Normal ▾
SME (Battery Management Electronics)	Normal ▾
EPS (Electronic Power Steering)	Normal ▾
CAS (Car Access System - CAS/FEM/BDC)	Normal ▾
GWS (Gear Selector Switch)	Normal ▾
HC/SWW (Lane Change Warning)/SRR_HR (Rear Radar Sensor Near Range Right)	Normal ▾
SAS2 (Optional Equipment System)	Normal ▾

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.